



10/535-158

Co/C

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of

**Attn: Certificate of
Correction Branch**

Yoshihiro KAWAKITA et al.

Patent No. 7,281,325

Atty Docket No. 2005_0748A

Issued October 16, 2007

Confirmation No. 5764

METHOD OF MANUFACTURING CIRCUIT
BOARD

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

**THE COMMISSIONER IS AUTHORIZED
TO CHARGE ANY DEFICIENCY IN THE
FEES FOR THIS PAPER TO DEPOSIT
ACCOUNT NO. 23-0975**

Sir:

In accordance with the provisions of 37 CFR 1.322, it is respectfully requested that a Certificate of Correction issue to correct the following:

In column 11, claim 8, line 13, "comprising" should be --comprises--.

Certificate

Dec 05 2007

of Correction

5/2007

REMARKS

Each of the errors listed above apparently arose due to PTO mistakes. Accordingly, a Certificate of Correction should issue at no expense to patentees. Form PTO-1050 accompanies this request.

Respectfully submitted,

Yoshihiro KAWAKITA et al.

By Walter C. Pledger
Walter C. Pledger
Registration No. 55,540
Attorney for Patentees

WCP/eo
Washington, D.C.
Telephone (202) 721-8200
Facsimile (202) 721-8250
December 3, 2007

To: The Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

PATENT NO : 7,281,325

DATED : October 16, 2007

INVENTOR(S) : Yoshihiro KAWAKITA et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 11, claim 8, line 13, "comprising" should be --comprises--.

Wenderoth, Lind & Ponack, L.L.P.
2033 K Street, N. W., Suite 800
Washington, D.C. 20006-1021

PATENT NO. 7,281,325

No. of additional copies

nfc 5 2007